

IMPORTANT INFORMATION: SILCA T80+

The Cloning Solution for Texas® 80 bit Ford®, Toyota®, Hyundai® and Kia®

The key should not be removed from the Silca RW4 Plus / Silca Fast Copy Plus / Ilco EZ®-Clone Plus during the Texas® 80 bit cloning procedure.

At a particular moment in the process if the key is removed or there is another interruption, such as a lost internet connection or the cloning device is switched off, there is a small chance that the original key may no longer work.

In this event the cloning device will automatically recognise that the original key no longer works and will begin a recovery procedure to restore the functionality of the original key.

- For Kia® and Hyundai® keys this process will work even without an internet connection.
- For Ford® keys an internet connection is needed. If an internet connection is not available the recovery procedure can be done with a diagnostic tool using the normal add or erase original key procedure.

